


Sechskant-Schweisssmuttern

Ecrous six pans
à souder

aus Stahl
blank

en acier
clair




d	s	m	d 1	h 1	h 2	100	1000
M 3	7,5	3,0	4,5	0,55	0,25	8.60	4.60
M 4	9	3,5	6,0	0,65	0,35	8.60	4.—
M 5	10	4,0	7,0	0,70	0,40	8.60	4.60
M 6	11	5,0	8,0	0,75	0,40	9.40	5.20
M 8	14	6,5	10,5	0,90	0,50	11.80	7.—
M 10	17	8,0	12,5	1,15	0,65	18.20	11.—
M 12	19	10,0	14,8	1,40	0,80	30.80	18.10
(M 14)	22	11,0	16,8	1,80	1,00	64.50	44.60
M 16	24	13,0	18,8	1,80	1,00	70.—	48.30
						100	

Vierkant-Schweisssmuttern

Ecrous carrés à souder

aus Stahl
blank

en acier
clair



d 1	s	e min.	m	h 1	h 2	d 2	100	1000
M 5	9	12	4,2	0,8	1,0	9	12.40	6.90
M 6	10	13	5,0	0,8	1,2	10	15.40	8.80
M 8	14	18	6,5	1,0	1,5	14	21.20	15.—
M 10	17	22	8,0	1,2	1,8	17	34.10	24.10
M 12	19	25	9,5	1,4	2,0	19	53.—	37.40
							100	