


Unterlagsscheiben ohne Fase

Rondelles sans chanfrein

VSM 13904

aus Stahl gestanz, 140 HV
blank

en acier estampé, 140 HV
clair



| für Schrauben pour vis | d 1 | d 2 | s | 100 | 500 | 1000 | 10000 |
|---------------------------|------|-----|-----|-------|-------|-------|-------|
| M 3 | 3,2 | 7 | 0,5 | 3.85 | 3.— | 1.80 | 0.50 |
| M 4 | 4,3 | 9 | 0,8 | 3.85 | 3.— | 1.80 | 0.50 |
| M 5 | 5,3 | 10 | 1 | 3.85 | 3.— | 1.80 | 0.50 |
| M 6 | 6,4 | 12 | 1,6 | 3.85 | 3.— | 1.80 | 0.90 |
| M 8 | 8,4 | 16 | 1,6 | 3.85 | 3.— | 1.95 | 1.50 |
| M 10 | 10,5 | 20 | 2 | 6.60 | 5.40 | 3.35 | 2.55 |
| M 12 | 13 | 24 | 2,5 | 7.50 | 5.90 | 4.70 | 4.15 |
| (M 14) | 15 | 28 | 2,5 | 10.— | 8.50 | 7.70 | 7.10 |
| M 16 | 17 | 30 | 3 | 10.10 | 8.60 | 7.80 | 7.10 |
| M 20 | 21 | 37 | 3 | 16.20 | 14.60 | 12.40 | 11.70 |
| (M 22) | 23 | 39 | 3 | 28.80 | 24.60 | 21.80 | 20.60 |
| M 24 | 25 | 44 | 4 | 28.80 | 24.60 | 21.80 | 20.60 |
| (M 27) | 28 | 50 | 4 | 47.40 | 37.90 | | |
| M 30 | 31 | 56 | 4 | 52.20 | 41.80 | | |
| M 33 | 34 | 60 | 5 | 90.— | 72.— | | |
| M 36 | 37 | 66 | 5 | 115.— | 92.— | | |
| | | | | 100 | | | |
| | | | | 50 | | | |

Toleranzen nach DIN 522 A/ISO 4759 / Tolérances selon DIN 522 A/ISO 4759