


## Unterlagsscheiben ohne Fase

für Schrauben mit schweren Spannhülsen

### Rondelles sans chanfrein


pour vis avec goupilles élastiques lourdes

aus Stahl gestanz  
**verzinkt-blau**en acier estampé  
**zingué-bleu**

für Schrauben pour vis	d 1	d 2	s	100	1000
M 3	3,2	9	1	7.80	3.50
M 4	4,3	12	1,6	7.80	3.50
M 5	5,3	15	2	8.30	5.90
M 6	6,4	17	3	15.—	11.—
M 8	8,4	21	4	24.60	17.80
M 10	10,5	25	4	29.40	21.90
M 12	13	30	6	57.—	42.10
(M 14)	15	36	6	100.50	73.50
M 16	17	40	6	102.—	75.—
M 20	21	44	8	132.—	96.50
(M 22)	23	50	8	194.—	142.—
M 24	25	50	10	252.—	184.—
(M 27)	28	60	10	313.—	229.—
M 30	31	68	10	384.—	280.—
				100	
				50	
				10	

## Unterlagsscheiben für Bolzen

### Rondelles rondes pour goujons

aus Stahl gestanz  
**verzinkt-blau**en acier estampé  
**zingué-bleu**

für Bolzen- $\phi$ pour goujons- $\phi$	d 1 H11	d 2	s	100	500	1000
3	3	6	0,8	4.60	3.85	3.30
4	4	8	0,8	4.60	3.85	3.30
5	5	10	0,8	4.95	4.15	3.60
6	6	12	1,6	7.60	6.40	5.60
8	8	16	2	13.20	11.10	9.10
10	10	20	2,5	17.60	15.—	12.30
12	12	25	3	27.50	23.40	18.70
16	16	28	3	31.—	26.40	21.60
18	18	30	4	50.80	43.20	38.50
20	20	32	4	57.—	49.20	43.10
22	22	34	4	64.—	55.—	48.10
23	23	36	4	69.—	59.—	51.60
24	24	38	4	83.50	69.50	60.—
25	25	40	4	91.—	78.50	69.—
26	26	40	5	125.—	109.—	97.—
28	28	42	5	135.—	118.—	103.50
30	30	45	5	152.—	134.—	119.—
36	36	52	6	188.—	168.—	147.—
				100		
				50		

Bestellgrösse d 1 x d 2 x s / Grandeur de commande d 1 x d 2 x s